
## CAMPGROUND/TRAILHEAD SIGN INSPECTION FORM

**CAMPGROUND:** Campo Alto **DATE:** 6/26/15 L.Brannan-FS, M.Subbotin Vol.

**SIGN #:** 1 **Or Location Description:** in front of campsite #4 at junction of entrance road and campsite spur road



Sign Type: Campground Entrance Sign Sign Wording: LPNF Campground Camp-O-Alto Spanis	h
Sign Info Size: ???? ⊠ Single-sided Sign □ Double-sided Sign	
<b>Type:</b> ⊠ Heavy Wood □ Light Wood □ Wood-Fiberglass/Plastic □ All Plastic □ Metal	
<b>Condition:</b> ☐ Good ☐ Fair ☐ Needs Paint ☐ Needs Repair and Paint ☐ Replace ☐ Remove	
Remarks (i.e. Repairs needed, etc): ????	

**SIGN #:** 2 **Or Location Description:** at junction of entrance road and campsite spur road



Sign Type: Bulletin/Info Board (Rec or Fire) Sign Wording: Forest Information: Rec Fee Area  Spanish
Sign Info Size: ??? ⊠ Single-sided Sign □ Double-sided Sign
<b>Type:</b> ☐ Heavy Wood ☐ Light Wood ☐ Wood-Fiberglass/Plastic ☐ All Plastic ☐ Metal
Condition: Good Fair Needs Paint Needs Repair and Paint Replace Remove
Remarks (i.e. Repairs needed, etc):
SIGN #: 3 Or Location Description: at junction of entrance road and campsite spur road and at group camps
PACK IT HE TAKE IT HE
Sign Type: Leave No Trace Sign Wording: Pack it In-Pack it Out Spanish
Sign Info Size: ?? ⊠ Single-sided Sign □ Double-sided Sign
<b>Type:</b> ☐ Heavy Wood ☐ Light Wood ☐ Wood-Fiberglass/Plastic ☐ All Plastic ☒ Metal
<b>Condition:</b> ☐ Good ☐ Fair ☐ Needs Paint ☐ Needs Repair and Paint ☐ Replace ☐ Remove
Remarks (i.e. Repairs needed, etc):

**SIGN #:** 4 **Or Location Description:** at junction of entrance road and campsite spur road



Sign Type: Miscellaneous Sign Wording: none Spanish	
Sign Info Size: ⊠ Single-sided Sign □ Double-sided Sign	
<b>Type:</b> ☐ Heavy Wood ☐ Light Wood ☐ Wood-Fiberglass/Plastic ☐ All Plastic ☐ Met	al
Condition: ☐ Good ☐ Fair ☐ Needs Paint ☐ Needs Repair and Paint ☐ Replace [	Remove
Remarks (i.e. Repairs needed, etc): ??purpose??	

**SIGN #:** 5 **Or Location Description:** on entrance road just before junction with campsite spur road



Sign Type: Directional	Sign Wording: Do Not Enter One Way Road Spanish
Sign Info Size: ??	∑ Single-sided Sign ☐ Double-sided Sign
Type: Heavy Wood	☐ Light Wood ☐ Wood-Fiberglass/Plastic ☐ All Plastic ☐ Metal
Condition: Sood [	☐ Fair ☐ Needs Paint ☐ Needs Repair and Paint ☐ Remove
Remarks (i.e. Repairs nee	ded, etc): 4x4 post rotten; replace post and reinstall

**SIGN #:** 6 **Or Location Description:** on exit road at junction with entrance road



Sign Type: Directional	Sign Wording: Do Not Enter One Way Road Spanish
Sign Info Size: ??	⊠ Single-sided Sign □ Double-sided Sign
Type: Heavy Wood	☐ Light Wood ☐ Wood-Fiberglass/Plastic ☐ All Plastic ☐ Metal
Condition: Sood	☐ Fair ☐ Needs Paint ☐ Needs Repair and Paint ☐ Replace ☐ Remove
Remarks (i.e. Repairs nee	eded, etc):